


How do you get this out to machine this area?



Note Wear?

(This must be welded and re-machined)