TYPICAL WIRING DIAGRAM (NO COWL LAMPS) 1928 TO MARCH 1929

