

SERVICE **HOUDAILLE** *Hydraulic Double-Acting* SHOCK ABSORBERS BULLETIN

SUBJECT NO. 18080 PAGE NO. 8


EXPORT SHOCK ABSORBER GUIDE SHEET
USE FOR PURCHASING NEW SHOCK ABSORBERS
1928-1940 MODELS INCLUSIVE




B-18015-B B-18016-B




48-18015-C 48-18016-C
R/R 33/34 L/R 33/34



O1A-18080-B O1A-18081-B



40-18045-B 40-18046-B
R/F 34 L/F 34



O1A-18045-D O1A-18046-D

Year	Car Model	Domestic or Export	RIGHT FRONT		LEFT FRONT		RIGHT REAR		LEFT REAR	
			Ford No.	Houde No.	Ford No.	Houde No.	Ford No.	Houde No.	Ford No.	Houde No.
1928–31	"A"	Both	B-18015-B	A-6406	B-18016-B	A-6407	B-18016-B	A-6407	B-18015-B	A-6406
1932	"B" "18"	Both	B-18015-B	A-6406	B-18016-B	A-6407	B-18015-B	A-6406	B-18016-B	A-6407
1933–34	"40"	Both	40-18045-B	A-6071	40-18046-B	A-6070	48-18015-C	A-5885	48-18016-C	A-5886
1935	"48"	Export	O1A-18045-D	A-6036	O1A-18046-D	A-6035	48-18015-C	A-5885	48-18016-C	A-5886
1936	"68"	Export	O1A-18045-D	A-6036	O1A-18046-D	A-6035	O1A-18080-B	A-6515	O1A-18081-B	A-6516
1937	"74" "78"	Export	O1A-18045-D	A-6036	O1A-18046-D	A-6035	O1A-18080-B	A-6515	O1A-18081-B	A-6516
1938	"81A" "82A"	Export	O1A-18045-D	A-6036	O1A-18046-D	A-6035	O1A-18080-B	A-6515	O1A-18081-B	A-6516
1939	"91A"	Export	O1A-18045-D	A-6036	O1A-18046-D	A-6035	O1A-18080-B	A-6515	O1A-18081-B	A-6516
1940	"O1A"	Export	O1A-18045-D	A-6036	O1A-18046-D	A-6035	O1A-18080-B	A-6515	O1A-18081-B	A-6516
1939	Mercury "99A"	Export	O1A-18045-D	A-6036	O1A-18046-D	A-6035	O1A-18080-B	A-6515	O1A-18081-B	A-6516
1940	Mercury "09A"	Export	O1A-18045-D	A-6036	O1A-18046-D	A-6035	O1A-18080-B	A-6515	O1A-18081-B	A-6516