05185780

VEHICLE INSPECTION REPORT

STATE OF COLORADO

RESULTS

Overall Result	Emissions	Evaporative Systems	Equipment Inspection	Smoke	CFC's	Recall	OBD Codes	Total Amount Paid
Fail	Fail	N/A	Pass	Pass	N/A	N/A	N/A	$ 15.00

VEHICLE INFORMATION

VIN	STATE	LICENSE PLATE	YEAR	MAKE	ODOMETER
			1953	MERCU	61994

PROGRAM	INSPECTOR #	LANE #	STATION #	START TIME	END TIME	DATE

CONSUMER INFORMATION

Your vehicle has failed to comply with required State regulations for emissions inspection. All items listed as failure must be addressed prior to your next inspection. See the box titled 'IF YOUR VEHICLE FAILED THE INSPECTION' for furthur instructions. If your vehicle failed emissions, see the box titled 'POSSIBLE CAUSES FOR EMISSION FAILURE' for further information.

EMISSIONS TEST INFORMATION

	Idle	2500	LIMITS	RESULTS
HC PPM	295	155	1000	Pass
CO %	5.86	1.08	3.50	Fail
CO2 %	11.2	13.8		
RPM	825	2461		

EVAPORATIVE SYSTEMS TEST INFORMATION

	PRESSURE	PURGE	FUEL CAP RESULTS
UNITS	INCHES/H_2O	N/A	
LIMITS	(6.0)	N/A	
READINGS		N/A	
RESULTS		N/A	Pass

EQUIPMENT INSPECTION INFORMATION

Catalytic Converter...: N/A
Fuel Filler Restrictor: N/A
Air Injection System..: N/A
Oxygen Sensor.....: N/A
Check Engine Light....: N/A

IF YOUR VEHICLE PASSED OR WAS ISSUED A WAIVER

Your vehicle inspection results are shown on this "VEHICLE INSPECTION REPORT". If you are renewing your registration by mail, follow the instructions regarding the renewal process located on the back side of your renewal notice. If you are renewing your registration in person, the Certificate of Emissions Control must accompany all supporting documents at the time of registration. If the Certificate of Emissions Control is lost, a new inspection is required at the owner's/operator's expense.

IF YOUR VEHICLE FAILED THE INSPECTION

Your vehicle inspection results are shown on this "VEHICLE INSPECTION REPORT". If your vehicle failed its first inspection, you are entitled to one free reinspection within 10 calendar days if returned to the same independent inspection station. If the first inspection was performed at an Envirotest center, the reinspection can be performed at any one of Envirotest's centers. The information recorded on this "VEHICLE INSPECTION REPORT" is extremely valuable to a repair technician when having your vehicle repaired. The "VEHICLE REPAIR FORM", (VRF), located on the back ***must*** be completed by the person performing the repairs. The VRF ***must also*** accompany the vehicle at the time of reinspection. If your vehicle fails the reinspection, you may be entitled to a waiver. Waiver eligibility information is available at the inspection stations or by calling the Department of Revenue at (303) 205-5603.

"QUALITY EMISSIONS REPAIRS ALWAYS BEGIN WITH A GOOD DIAGNOSIS BY A QUALIFIED REPAIR TECHNICIAN."

HIGH HC READINGS	HIGH CO READINGS	HIGH NOx READINGS
HIGH HC READINGS ARE A RESULT OF UNBURNED OR PARTIALLY BURNED FUEL.	HIGH CO READINGS OCCUR WHEN THE AIR/FUEL MIXTURE IS TOO RICH.	HIGH NOx READINGS ARE THE RESULT OF HIGH COMBUSTION TEMPERATURES AND/OR HIGH COMBUSTION PRESSURES. *(ENHANCED AREA ONLY)*

INSPECTION TYPE XXXXXXXX

05185780

DATE XX-XX-XXXX FACILITY # XXXXXXXX

INSPECTOR # XXXXXXXX LICENSE # XXXXXXXX

MAKE XXXXXXXX MODEL XXXXXXXX YEAR XXXX

VIN # XXXXXXXX

PLEASE REMOVE THIS PORTION AND INCLUDE IT WITH YOUR RENEWAL CARD AND REGISTRATION PAYMENT. DO NOT STAPLE THIS DOCUMENT OR PAYMENT TO YOUR RENEWAL CARD.