A-7121 long cluster bearing

I noticed three things which are not normal for a bearing

-- the rivet head protrude over the washer

-- the washer left and right are very wavy

the whole item is a real parallelogram



